Fig. 53: Base Radio Circuit



© 2005 Mitchell Repair Information Company, LLC.